



EA6114

EA6114 is a high performance, fluorescence, fast cure, UV/moisture dual cure adhesive/encapsulant. EA6114 is optimized for fast moisture curing supporting increased manufacturing productivity. This product is suitable for bonding a wide variety of substrates including glass, many plastics and most metals. This product has a tack free surface finish and has shown excellent adhesion and flexible. It can be moisture cured in shadowed areas.

Technology / Base	Polyurethane Acrylate	
Type of Product	Adhesive and Encapsulant	
Components	One Component	
Curing	Ultra Violet Light and Ambient Moisture	
Appearance / Color	Translucent	
Consistency	Thixotropic Liquid	

Features and Benefits

- Fast cure
- UV/moisture dual cure
- High adhesion strength
- Rapid moisture curing
- Excellent flexibility
- Tack free surface finish
- Excellent precision dispensing and jetting performance
- Excellent electrical insulation performance
- Halogen free

Technical Data			
Rheology	Value	Condition/Method	
Viscosity	5100 cPS	25°C (77°F)	
Thixotropic Index	2.4		
Density			
Specific Gravity	1.05		
Curing Process Characteristics			
Cure Time and Wavelength	30s at 100mW/cm2, 365nm, Moisture cure at 25°C 50% RH for 3 days		
Shelf Life	6 months		
Storage Condition	8°C to 28°C in unopened container, dry location		
Optimum Wavelength	365 to 405 nm		
Cured Material Characteristics			
Tack Free	5s at 100mW/cm2, 365nm		
RoHS Compliant	Yes		
Cured Mechanical Properties			
Hardness Shore A		ASTM D2240, UV plus 3 day moisture c	
Shore D	75	ASTM D2240, UV plus 3 day moisture c	
Tensile Strength	19 MPa	ASTM D638	
Elongation to Break	95%	ASTM D638	
Lap Shear Strength, PC/PC	16.2 MPa	ASTM D1002, 25°C 50% RH 3 days	





General Instructions

- 1. Coating surface area should be clean and free of any fluxes, residues, dust or any other contaminants.
- 2. A UV lamp with a wavelength of 365nm is required. The UV light should be focused towards the coated surface.
- 3. Curing speed is determined by the intensity of UV radiation, the distance from the UV light source and the coating surface. The depth of coating material can also require additional cure time.
- 4. Immediately close the lid after use. A black hose must be used to dispense the adhesive.
- 5. This material should be stored away from sunlight, UV light and artificial light sources.

H.B. Fuller Company No. 27 Chongging Street Yantai Economic and Technological Development Zone Yantai, Shandong, China 264006 + 86-535-610-8822 tel

Specifications and Approvals

ISO 10993-5

Storage

Product should be stored at temperature between 8°C to 28°C in the unopened container in a dry location.

Safety and Disposal

For safe handling information and disposal information on this product, consult the Safety Data Sheet (SDS)

Date Modified: 11 January 2019

www.hbfuller.com

Connecting what matters.™

IMPORTANT: Information, specifications, procedures and recommendations provided ("information") are based on our experience, and we believe this information to be accurate. No representation, guarantee or warranty is made as to the accuracy or completeness of the information or that use of the product will avoid losses or damages or give desired results. It is purchaser's sole responsibility to test and determine the suitability of any product for the intended use. Tests should be repeated if materials or conditions change in any way. No employee, distributor or agent has any right to change these facts and offer a guarantee of performance.

® and ™ are trademarks of H.B. Fuller Company or one of its affiliated entities.



H.B. Fuller www.hbfuller.com